## Oil Field Environmental Incident Summary

**Responsible Party:** Badlands Power Fuels **Well Operator:** HESS CORPORATION

Well Name: BROSTUEN 6-1H

Field Name: GLASS BLUFF Well File #: 19219

Date Incident:12/7/2012Time Incident:08:00Facility ID Number:County:MCKENZIETwp:151Rng:102Sec:6Qtr:

Location Description:

Submitted By: Derek Klang Received By:

Contact Person: Connie Rhone

3711 4th Ave.NE

Watford City, ND 58854

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 2 Miles

Distance Nearest Water Well:

Type of Incident: Truck Overflow

0

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No Spilled **Units** Recovered Units **Followup Units** 0 Oil 0 barrels barrels **Brine** 8 barrels 0 barrels barrels

barrels

**Description of Other Released Contaminant:** 

barrels

Inspected: Written Report Received: 12/26/2012 Clean Up Concluded: 12/8/2012

Risk Evaluation:

none

Other

Areal Extent:

## Potential Environmental Impacts:

minimal as the ground is frozen. Powser Fuels will start clean up on the morning of 12/8/2012

## Action Taken or Planned:

Area was diked with dirt from location to stop any further spread. will clean the area and dispose of at their land teck disposal site.

Wastes Disposal Location: Landtech disposal

Agencies Involved:

## **Updates**

Date: 12/10/2012 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Release remained on location and was diked with location materials according to report.